


**NYS Department of Environmental Conservation
Division of Environmental Remediation
Bureau of Hazardous Site Control
50 Wolf Road, Albany, New York 12233-7010**



**John P. Cahill
Commissioner**

October 9, 1997

Mr. Peter Koutroubis
BRAC Environmental Coordinator
Department of the Army
New York Area Command and Fort Hamilton
Directorate of Public Works, Bldg. 129
Environmental Division
Brooklyn, NY 11252-6800

Re: **Groundwater Data - 3rd Round
Fort Totten (BRAC Area)
NYSDEC Site ID #241017A**

Dear Peter:

I have received and reviewed the groundwater data from samples collected on July 15, 1997 at the above-mentioned site.

Based on this data, I recommend taking a 4th round of groundwater samples during the next round of work as follows:

Monitoring Well

FTMW01
FTMW02
FTMW03
FTMW09
FTMW10

Parameters

metals
VOCs
VOCs, metals
metals
VOCs

Please contact me at (518) 457 - 0639 if you have any questions on this letter or require further information.

Sincerely,

David K. Harrington
Environmental Engineer 1
Eastern Investigation Section
Bureau of Hazardous Site Control

